

1/9




FIG. 1

2/9




FIG. 2

3/9




FIG. 3

4/9




FIG. 4

5/9





FIG. 5

4 2 a			4 2 b		4 2 c	
HISTORY DATA			NUMBER OF DATA		12	
VEHICLE NUMBER	品川 501あ1388	PERIOD	2002・02・22	14:30 ~ 16:30		

NO.	TIME	VEHICLE POSITION (PLACE NAME)	SPEED	DIRECTION	LOADAGE	DELIVERY QUANTITY	LOSS QUANTITY
1	14:30:00	XX COMPANY, NIHONBASHI 2-CHOME, CHUO-KU, TOKYO	65	SOUTHEAST	0.79t	0.40t	0.06t
2	14:20:00	VICINITY OF TAKEBASHI 3-CHOME, CHIYODA-KU, TOKYO	15	EAST	1.25t	.	—
.
.
.

4 2 d 4 2 e 4 2 f 4 2 g 4 2 h 4 2 i 4 2 j 4 2 k

FIG. 6






FIG. 8

9/9




FIG. 9